STATE OF NEW JERSEY DEPARTMENT OF LAW AND PUBLIC SAFETY

DIVISION OF STATE POLICE BREATH TESTING INSTRUMENTATION SERVICE REPORT						
			RVICE REPO			
1. Department:	1	2. Contact:		4. Date:		
Brielle Police Department 601 Union Lane		Ron Sofield		3/23/21		
Brielle, NJ 08730	200000	3. Phone Number:		5. County:		
6. Alcotest Instrument Serial Number:		732-528-5050		Monmouth		
	7. Simulator Compone		8. Temperatu	ure Probe Component Serial Number:		
ARWM-0073	ž.	NA		NA		
9. Reason for Service: Complaint received of the institution	rument experienci	ng control test fa	ilures.	in the second se		
10. Comments:						
Operational condition of the in instrument. This revealed con instrument was placed out of s	trol test failures du ervice and returne	ie to low electroc	chemical senso	or (EC) results. The		
11. The above Instrument/Compon		ne in satisfactory work	king condition: no	further action required		
			0000	7-11-11-11		
The state of the s						
"I have been certified by the Attorney General as a Breath Test Coordinator/Instructor pursuant to N.J.A.C. 13:51, et. seq. In my official capacity as a Breath Test Coordinator/Instructor I perform inspections of evidential breath test devices and related components of evidential breath test systems. I have inspected the evidential breath test device listed on this report in my official capacity. The results of my inspection are recorded on this form. I certify that the forgoing statements made by me are true and accurate to the best of my knowledge. I am aware that if any of the forgoing statements made by me are willingly false, I am subject to punishment."						
Tpr. I Dennis J. Lutz #70	045	To T	Dent.	7045 3-23-21 Date		

STATE OF NEW JERSEY DEPARTMENT OF LAW AND PUBLIC SAFETY

DIVISION OF STATE POLICE BREATH TESTING INSTRUMENTATION SERVICE REPORT							
1. Department:	2. Contact:	4. Date:					
Brielle Police Department	Ron Sofield	04/26/21					
601 Union Lane	3. Phone Number:	5. County:					
Brielle, NJ 08730	732-528-5050	Monmouth					
Alcotest Instrument Serial Number:	7. Simulator Component Serial Number:	8. Temperature Probe Component Serial Number:					
ARWM-0073	NA	NA					
9. Reason for Service:	IVA	NA.					
	turned from outside evaluation and	placed back in service.					
10. Comments:							
See Draeger Return and Repair	r form.						
Last Known Sequential							
11. The above Instrument/Compone	ent has been found to be in satisfactory worki	ng condition; no further action required.					
12. The above Instrument/Component is placed out of service pending further evaluation.							
X 13. The above Instrument/Component is placed back in service.							
official capacity as a Breath Test Co components of evidential breath test sy capacity. The results of my inspection accurate to the best of my knowledge. subject to punishment." Tpr. I Dennis J. Lutz #70	stems. I have inspected the evidential breath are recorded on this form. I certify that the I am aware that if any of the forgoing state	tor pursuant to N.J.A.C. 13:51, et. seq. In my of evidential breath test devices and related test device listed on this report in my official forgoing statements made by me are true and ements made by me are willingly false, I am					
Name & Badge Number (Print)	Signature	Date					

RETURN AND REPAIR FORM



Customer Information	В	S					
Company Name: Borough Of E	Brielle, Brielle, NJ						
Date Received: 03/25/2021		Date given to service: 03/25/2021					
Carrier: FedEx UPS	USPS S hi	pping Method: GRD 3DAY 2DAY NDA-PRI NDA-STD					
Product: 6510 × 7110	6810 8610	Serial Number: AR WM-0073 Printer Serial#: AR					
7510	DT5000						
7410 Upper-ha	alf 9510	9510 Sim Serial#: DD					
7410 Whole	7410 Whole Probe Serial#: DD						
		Warranty Expires:					
Description: A B	Plus Demo	Screener Trade In					
Accessories	i i i di dinamenti etti i 2. 1960-yilli. P						
110V A/C Adapter Mouthpieces Dry Gas	Regulator 9510 Stylus Other (please	e specify)					
Repair Information: Part Number	Description	Test#. Oty Total Cost					
MP Cal 71	Calibration	2.0					
MP Labor	Labor	.5					
6808455	Fuel Cell	1					
6808374	Geared Engine	1					
		-					
Repair Notes: Replaced defective	e fuel cell and gea	red engine.					
FUEL CELL = ARND-1618							
CAL W/QC AND OPS CHECK	<						
ervice Technician	OR	Date: 04/16/2021					

sustcfs010\Public\Forms\return and repair form 07_21_2011.pdf



Delivery receipt

Customer no. 150061056 Number of report 305963500

Please reference on inquiries

Consignee, 150061057

BRIELLE BOROUGH POLICE DEPARTMENT ATTN:LT STEPHEN BOYD PO#ARWM-0073 601 UNION LN BRIELLE NJ 08730-1494

Date of receiving Delivery receipt date

04/19/2021

Customer, 150061056 BOROUGH OF BRIELLE ATTN: FINANCE DEPARTMENT PO#ARWM-0073 PO Box 445 BRIELLE NJ 08730-0445

Your order

Date of order: 03/23/2021 Purch.ord.no.: 21-00540

Draeger contact person

Service Support-IDT 800-437-2437 OPT 5 SS-IDT@draeger.com

Branch text

Page 1

Quantity 001	Description ALCOTEST 7110 MK III USA	Equipment - No. 1024506477	Serial - No. ARWM-0073

Service note

Customer no.

Number of report

Date of receiving

150061056

305963500

03/23/2021

Please reference on inquiries

Customer

BOROUGH OF BRIELLE

ATTN: FINANCE DEPARTMENT

PO Box 445

BRIELLE NJ 08730-0445

Consignee

BRIELLE BOROUGH POLICE DEPARTMENT

ATTN: PTL. RONALD SOFIELD

601 UNION LN

BRIELLE NJ 08730-1494

Your order

Date of order: 03/23/2021

Your reference:

21-00540

NL-Text

Maintenance device list

Your contact person

Service Support-IDT 800-437-2437 OPT 5 SS-IDT@draeger.com

Quantity

1

1

EΑ

EA

Page 1

Item

Part no. Description

Service Order: 144577656

REPAIR/ARWM-0073

Eq.No. : 1024506477 SN: ARWM-0073

Material: 8314246 ALCOTEST 7110 MK III USA

Inv.No. :
Location:

REPAIR/ARWM-0073

0.5 H R001 Repair time - normal hours

6808455 Sensor Alcotest B

6808374 Geared Engine, A7110/A9510